



NRD, LLC | 800-525-8076
 2937 ALT BOULEVARD | 716-773-7634
 PO BOX 310 | 716-773-7744 FAX
 GRAND ISLAND, NY | www.nrdinc.com
 14072-0310 | sales@nrdinc.com

**Return shipping instructions for articles
 STATICMASTER**

As a guide to proper packaging and shipping, please follow these instructions:

1. Maximum allowable activity of each package is 541 mCi (20,000 MBq) (ref: 49CFR 173.425, Table 4; I.A.T.A. Sec. 10, Table 10.5.A). Radiation level at any point on the external package must not exceed 0.5 mrem/hr (0.005 mSv/hr) (ref: 49CFR 173.421). The non-fixed or removable radioactive contamination on the external surface shall not exceed 22 dpm/cm² (ref: 49CFR 173.443).
2. The package should be new, no smaller than 4" x 4" x 4", have no protrusions, and be capable of withstanding normal transport conditions. Tape all seams and flaps with nylon reinforced tape so that there are no openings. (ref: 49CFR 173.410)
3. The following address (A) and statement or label must be on the package. The UN number (B) is added for ground freight only. The label (C) is added for airfreight only, with "2911" written in for UN number.


A. Shipping address:

NRD, LLC
2937 Alt Blvd.
Grand Island, NY 14072

B. Ground freight only:

UN2911

C. Airfreight only



4. **Send package to NRD, LLC, prepaid.** Shipping costs, taxes and/or duties are the shipper's responsibility. Mark all export documents and Airway Bill or Bill of Lading "DDP Grand Island, NY" (Deliver Duties Paid to Grand Island, NY). If shipping via US mail, please refer to the correct instruction sheet.

NOTE: IT IS THE SHIPPER'S/SENDER'S RESPONSIBILITY TO BE TRAINED FOR HAZARDOUS MATERIALS SHIPPING.